

RASPBERRY PI ASSEMBLY






RASPBERRY PI ASSEMBLY


0. Collect Raspberry Pi, Assembled Pi Camera, Battery, 2 Rubber Bands, 3 Standoffs, 3 screws (plus 3 extras), LCD Screen, and Lasercut Case



1. Plug in Raspberry Pi Camera




2. Plug in LCD Screen






RASPBERRY PI ASSEMBLY

3. Align standoffs as shown and secure them by partially screwing from LCD side



4. Flip Raspberry Pi (LCD down) and place laser cut case on top as shown, and then place the pi camera on top of the case, aligning the holes as shown in the second photo.



5. Screw down the pi camera and pi laser cut case. Do not fully tighten. Use tweezers to hold standoffs





RASPBERRY PI ASSEMBLY

6. Remove screws on LCD side. Fully tighten screws holding the pi camera.



7. Put battery into slot and use two rubber bands to secure it on the hooks.



8. Plug in your finished Product!





Resource: Girls Who Build Cameras

Kristen Railey, Bob Schulein, Olivia Glennon, Leslie Watkins, Alex Lorman, Carol Carveth, and Sara James

The following may not correspond to a particular course on MIT OpenCourseWare, but has been provided by the author as an individual learning resource.

For information about citing these materials or our Terms of Use, visit: https://ocw.mit.edu/terms.